

THERMOSTAT HOUSING ENGINE COOLANT LEAK – I4/2.0L

Customer Voice:

- Low engine coolant lamp warning on instrument panel and/or coolant leak.

Technical Description:

- Possible leak at thermostat housing at welded spigot cap

Status:

- If you have diagnosed an engine coolant leak at the thermostat housing, proceed to repair the vehicle
- Please raise an Electronic Product Quality Report (EPQR) and include the below information:
 - Photographs/video evidence of the thermostat housing engine coolant leak (before parts are removed from the vehicle)
 - Photographs/video evidence of the thermostat housing removed from the vehicle and any obvious defects/leak paths.

Range Rover

- 20-24MY Evoque
- 20-24MY Velar

Defender

- 20-24MY Defender

Discovery

- 20-24MY Discovery
- 20-24MY Discovery Sport

Jaguar

- 20-24MY E-PACE
- 20-24MY F-PACE
- 20-24MY XF
- 20-21MY XE

Refer to SSM 76249/ SSM 76248

