

COOLANT LOSS THROUGH ENGINE COOLANT EXPANSION CAP

Customer Voice:

- Low engine coolant lamp warning on instrument panel and/or coolant leak at expansion tank cap.

Technical Description:

- Coolant expansion tank cap will not hold pressure when tested.

Status:

- Follow the procedure as in Topix 303-03C: Engine Cooling, system pressure test
- Replace the engine coolant expansion tank cap if that is found to be at fault, but do not discard the removed part, it will be required for a Parts Return Request (PRR) which will be arranged by the relevant JLR Engineering team.
- Please raise an Electronic Product Quality Report (EPQR) which should include the information
 - Attach any photographic evidence
 - Reference the SSM
 - Confirm you have the part for PRR

Range Rover

- 23-24MY Velar

Defender


- 23-24MY Defender

Discovery

- 23-24MY Discovery

Jaguar

- 23-24MY F-TYPE
- 23-24MY F-PACE
- 23-24MY XF
- 23-24MY XE



Refer to SSM 76255/ SSM 76258