

ELECTRIC PARK BRAKE SWITCH INOPERATIVE

Customer Voice:

- The parking brake switch sticks or does not work.

Technical Description:

- This may be caused by debris built up in the area surrounding the edge of the EPB switch.

Status:

- SSM 76230 & 76231 have been published to provide diagnosis and repair should a customer express a concern.
- Parts should not be replaced before cleaning is performed
- **Please Note:** debris piled into switch area is not a manufacturing defect and not covered by warranty.

Range Rover

- 23MY- On Range Rover
- 23MY-On RR Sport
- 21MY-On RR Velar

Discovery

- 21MY-On Discovery

Jaguar

- 21MY-On F-PACE
- 21MY-On E-PACE

