

Reference	SSM76230
Models	Discovery / L462 New Range Rover / L460 New Range Rover Sport / L461 Range Rover Velar / L560
Title	Electric Park Brake (EPB) Switch Inoperable Due To Build-Up Of Debris
Category	Body
Last modified	04-Feb-2025 00:00:00
Symptom	107000 Interior Trim
Attachments	Attachment 16.JPG (Attachment 16.JPG)
Content	<p>Model / Model Year / Derivative:</p> <p>Range Rover / 22MY Onwards / All Range Rover Sport / 23MY Onwards / All Range Rover Velar / 21MY Onwards / All Discovery / 21MY Onwards / All</p> <p>Situation:</p> <p>The Electric Park Brake (EPB) switch becomes stuck and inoperable.</p> <p>Cause:</p> <p>Debris build-up in the area surrounding the edge of the EPB switch.</p> <p>Action:</p> <p>Refer to the service information below.</p> <p>Service Information:</p> <p>Using compressed air, gently blow any debris out of the area surrounding the EPB switch until the switch can be operated freely. See 'Attachment 1' for guidance.</p> <p>(Ref 000340121 / 76230 / 76231)</p> <p><small>anBhdhRlcnM7MjAyNS0wMj0wNFQxND01MD00NC40NzRaOzE2NS4yMjUuOS42OTs=</small></p>