

Reference	SSM76231
Models	E-PACE / X540 F-PACE / X761
Title	Electric Park Brake (EPB) Switch Inoperable Due To Build-Up Of Debris
Category	Body
Last modified	04-Feb-2025 00:00:00
Symptom	107000 Interior Trim
Attachments	Attachment 13.JPG (Attachment 13.JPG)

Content

Model / Model Year / Derivative:

F-PACE / 21MY Onwards / All
E-PACE / 21MY Onwards / All

Situation:

The Electric Park Brake (EPB) switch becomes stuck and inoperable.

Cause:

Debris build-up in the area surrounding the edge of the EPB switch.

Action:

Refer to the service information below.

Service Information:

Using compressed air, gently blow any debris out of the area surrounding the EPB switch until the switch can be operated freely. See 'Attachment 1' for guidance.

(Ref 000340121 / 76230 / 76231)

anBhdhRlcnM7MjAyNS0wMj0wNFQxND00MjpwMy4wMTFzOzE2NS4yMjUuOS42OTs=