

Reference	SSM76258
Models	F-PACE / X761 F-TYPE / X152 XE / X760 XF / X260
Title	Coolant Loss Through Engine Coolant Expansion Tank Cap
Category	Engine
Last modified	04-Feb-2025 00:00:00
Symptom	402000 Cooling System Concerns
Content	<p>Model / Model Year / Derivative</p> <p>F-PACE / 23MY onwards / All derivatives XE / 23MY onwards / All derivatives XF / 23MY onwards / All derivatives F-TYPE / 23MY onwards / All derivatives</p> <p>Situation:</p> <p>JLR Engineering investigations have identified a number of vehicles where the engine coolant expansion tank cap has been replaced due to slight seepage or the engine coolant expansion tank cap not holding pressure when pressure tested.</p> <p>Cause:</p> <p>Under investigation. Completing the actions within the service request below will assist Engineering in determining root cause.</p> <p>Action:</p> <p>Refer to the service request below.</p> <p>Service Request:</p> <p>In instances where the engine coolant expansion tank cap requires replacement due to slight seepage, or the engine coolant expansion tank cap not holding pressure when pressure tested, replace the engine coolant expansion tank cap but do not discard the removed part, it will be required for a Parts Return Request (PRR) which will be arranged by the relevant JLR Engineering team.</p> <p>Raise an Electronic Product Quality Report (EPQR) which must include the information below:</p> <ul style="list-style-type: none"> • Reference to PTS_500 • Reference to P373122 • Reference to this SSM (SSM76258) • Any relevant photographs • Confirmation that the removed part(s) are being retained for collection by PRR <p>(Ref 000373122 / 3931)</p>

