



**SSM 53465 2021-2024 Bronco Sport, 2020-2024
Escape/Corsair/Edge/Nautilus/Transit Connect, 2022-2024 Maverick - Erratic
Shift And/Or Fluid Venting - Engine Coolant In Transmission Fluid**

Some 2021-2024 Bronco Sport, 2020-2024 Escape/Corsair/Edge/Nautilus/Transit Connect and 2022-2024 Maverick vehicles may exhibit erratic shifting and/or a transmission fluid venting condition. If during the preliminary inspection the transmission fluid is found to be a foamy pink color, this may indicate possible cross contamination of engine coolant and transmission fluid due to an internally leaking transmission fluid cooler assembly. When repairing or replacing the transmission assembly for an internally leaking transmission fluid cooler assembly, use causal part 7869 and applicable labor operations in Section 07 of the Service Labor Time Standards (SLTS) Manual.