



**Bulletin No.:** PIP5929C

**Published date:** 03/7/2025

## Preliminary Information

### PIP5929C Diagnostic Tip for DTC P219A Setting with No Other Drivability Symptoms

#### Models

| <b>Brand:</b> | <b>Model:</b> | <b>Model Years:</b> | <b>VIN:<br/>from to</b> | <b>Engine:</b>       | <b>Transmissions:</b> |
|---------------|---------------|---------------------|-------------------------|----------------------|-----------------------|
| Buick         | Encore GX     | 2020 - 2025         | All                     | All 1.2L LIH and LBP | All                   |
| Buick         | Envista       | 2024 - 2025         | All                     | All 1.2L LIH and LBP | All                   |
| Chevrolet     | Trailblazer   | 2021 - 2025         | All                     | All 1.2L LIH and LBP | All                   |
| Chevrolet     | Trax          | 2024 - 2025         | All                     | All 1.2L LIH and LBP | All                   |

|                                   |   |
|-----------------------------------|---|
| <b>Involved Region or Country</b> | <b>North America</b>                        |
| <b>Condition</b>                  | <b>MIL on with P219A stored in history.</b> |
| <b>Cause</b>                      | <b>Potential fuel injector issue.</b>       |

#### Correction:

If you encounter DTC P219A set in history and this is first failure occurrence please clear the code using GDS and evaluate to see if the DTC will return.

If the DTC P219A returns replace the three fuel injectors and evaluate the condition.

#### Version History

|                 |  |
|-----------------|--|
| <b>Version</b>  | <b>4</b>   |
| <b>Modified</b> | <b>6/16/2023 - Created.</b><br><b>12/16/2024 Updated Models and RPO code.</b><br><b>01/17/2025- Updated Models and RPO code.</b><br>03/07/2025 - Updated Models. |