



## **SSM 53495 2016-2020 F-150 - Illuminated MIL With DTC P0630 Stored In The PCM**

Some 2016-2020 F-150 vehicles may exhibit an illuminated malfunction indicator lamp (MIL) with diagnostic trouble code (DTC) P0630 stored in the powertrain control module (PCM). This may be due to aftermarket modifications to the body control module (BCM), such as changes to the tire size or axle ratio in the BCM. To repair this condition, configure the BCM with as-built data using the Integrated Diagnostic System (IDS). When IDS prompts "Were you directed here from another procedure such as Programmable Module Installation or Module Reprogramming to obtain part numbers?", select "No".