

REFERENCE:	TSB: 08-016-25 REV. A GROUP: 08 - Electrical	Date:	March 18, 2025	REVISION:	08-016-25
VEHICLES AFFECTED:	2025 (DT) RAM 1500 Pickup This bulletin applies to vehicles equipped with a Wireless Charging Pad (Sales Code RFX) or Dual Wireless Charging Pad (Sales Code CMS).	MARKET APPLICABILITY:			
		<input checked="" type="checkbox"/> NA		<input checked="" type="checkbox"/> MEA	
		<input checked="" type="checkbox"/> SA		<input checked="" type="checkbox"/> IAP	
		<input type="checkbox"/> EE		<input type="checkbox"/> CH	
CUSTOMER SYMPTOM:	Customers may comment on the following: <ul style="list-style-type: none"> Key Fob intermittently is not detected when the key fob is placed at or near the wireless charger. 				
CAUSE:	Radio Frequency (RF) interference				

This bulletin supersedes Technical Service Bulletin (TSB) 08-016-25, date of issue January 23, 2025, which should be removed from your files. All revisions are highlighted with ****asterisks**** and updated text on how to verify Symptom/Condition.

DISCUSSION:

- NOTE:**
- The key fob needs to be at least 203 mm (8 in.) away from the wireless charger and/or do not put a phone on the wireless charger before the ignition is ON.
 - When the ignition is OFF and the key fob near an active wireless charger, interference can occur leading to the key fob not being detected by the vehicle **Fig. 1**.

****To verify if the vehicle has this Symptom/Condition, perform the following: Remove any phones from the wireless charger. Verify if the key fob functions/is detected now. If key fob functions/is detected now, replace charger.****



Fig. 1
Key Not Detected

POLICY:

Information Only.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.