

Technical Service Bulletin (TSB)
Missing Charging Cable Bag

REFERENCE:	TSB: 23-012-25 GROUP: 08 - Electrical	Date:	March 19, 2025	REVISION:	-
VEHICLES AFFECTED:	2024 - 2025 (MV) Jeep Compass (Italy) This bulletin applies to vehicles built on or after September 26, 2024 (MDH 0926XX) and on and before January 26, 2025 (MDH 0126XX) equipped with the 1.3l I4 Turbo PHEV Engine (Sales Code EYG) .			MARKET APPLICABILITY:	
				<input type="checkbox"/> NA	<input type="checkbox"/> MEA
				<input type="checkbox"/> SA	<input type="checkbox"/> IAP
				<input checked="" type="checkbox"/> EE	<input type="checkbox"/> CH
CUSTOMER SYMPTOM:	Customers may experience the following: <ul style="list-style-type: none"> Missing black bag for the charging cable MODE 3. 				
CAUSE:	ODM misunderstood by plant				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 25-035, date of issue March 19, 2025. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves ordering a new charging cable bag and placing it in the vehicle.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-08-03-95	Bag, Charging Cable Missing (0 - Introduction)	6 - Body and Electrical	0.1 Hrs.
Failure Code	ZY	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1	7BX48LXHAA - MOPAR 735716718 - EMEA	Bag, Storage	

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Order a charging cable bag using the vehicle's VIN number.
2. Open the trunk compartment.
3. Insert the black charging cable bag.
4. Close the trunk compartment.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.