

Technical Journal

TITLE:

Changed front fog/cornering lights behavior

REF NO: TJ 37289.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7515 Polestar		ISSUE DATE: 2025-02-21	STATUS DATE: 2025-02-26
FUNC GROUP: 3520	FUNC DESC: Lighting, front	Page 1 of 2	

DESCRIPTION:

If a customer complains about different light behavior of the front fog lights/cornering lights, follow advice under "Service".

CSC Customer Symptom Codes

Code	Description
FM	Exterior light front (excl headlight)/Fog lights do not work

DTC Diagnostic Trouble Codes**Vehicle Type**

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
534							2021-2025		-	201935-202446

SERVICE:

This is information about a logic change for the front bumper cornering lights. The change will not be corrected.

Before the logic change, the cornering light turned on when putting gear in reverse and turned off again when going out of reverse. This logic of the cornering lights is now changed in the cars with software version 3.3.16 or later. The change appear when shifting gear from reverse to any other gear, the cornering lights will remain on until driving forward $\geq 10\text{km/h}$ ($\geq 7\text{mph}$), then they will go off.

Please note, the lower mounted front bumper lamps are used for both the cornering light and fog light function which operate independently.

Technical Journal 37289.1.0

Warranty claim info:

No warranty claim is accepted for this TJ.

LABOR TIME:

Labor time subject to change without notice.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3520.