

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title EX90 PDS software upgrade - Best Practice		Ref. No. TJ 37276.1.1	
Issuer (Dept.) Technical Service		Issue Date 2/14/25	Status Date 2/25/25
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 3808	
Function Description Software		Page Page 1 of 1	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

If you are performing a PDS software upgrade, follow the advice under "Service".

CSC Customer Symptom Codes

Code	Description
1Z	Service/repair/Software update failed

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
356							2025-9999		-	202417-999952

SERVICE:

Please follow the below revised order of task or check list while performing PDS software upgrade on an EX90.

1. Perform a PDS software upgrade.
2. Bring the car from transport mode to normal mode (this includes removal of speed restriction)

The VIDA checklist is being updated and changes will be reflected soon.

Reference: Service Product Journal SJ 1002474 has been released.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3808.