



STAR ONLINE PUBLICATION



Case Number: S2518000001

Release Date: March 2025

Symptom/Vehicle Issue: Malfunction Indicator Lamp (MIL) Illumination. Diagnostic Trouble Code (DTC) P0315 – No Crank Sensor Learned.

Discussion: Some customers may experience a MIL illumination. Upon further investigations, the technician may find DTC P0315 setting in the Powertrain Control Module (PCM). This condition may occur on vehicles with low mileage or may be seen during Pre-Delivery Inspection (PDI).

If you receive a vehicle with the above condition, do not replace any parts at this time. This issue is currently under investigation for a possible upcoming software update.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.