



SSM 53519 2020-2025 Explorer/Aviator - 3.0L EcoBoost - Left Turbocharger Oil Supply Tube Procedure Update

Some 2020-2025 Explorer/Aviator vehicles equipped with a 3.0L EcoBoost engine may require removal of the left turbocharger oil supply tube due to various concerns. Workshop Manual (WSM), Section 303-04 has been updated with improved left turbocharger oil supply tube removal and installation service procedure steps.