

SERVICE BULLETIN 629 – TIGER SPORT 800

SERVICE BULLETIN 629 – TIGER SPORT 800: ABS MODULATOR FRONT BRAKE MASTER CYLINDER & FRONT BRAKE CALIPER HOSE CONNECTIONS

Subject: Front Brake Hose Alignment			
Bulletin Number	Models Affected	VIN Range	Markets Affected
629	Tiger Sport 800	From CE7729 to CG6198	Canada, North America, Japan Markets Only

Dealers are requested to check and, if necessary, reroute the front brake master cylinder hose and front brake caliper hose at the ABS modulator as described in the outlined in **Service Bulletin 629**, found in the Technical Information section of [TriumphOnline.net](https://www.triumphonline.net).

Service Bulletin 629

 Triumph Technical Information_SB629.pdf

Reminder: use the "[VIN Enquiry](#)" function within TOL to search for any outstanding bulletins or recalls whenever a new bike arrives, or a Triumph owner visits your dealership.

Note:

- Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.
- Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on www.triumphonline.net.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.