

TIGER 1200 HEADLIGHT DOWNLOAD ERROR: TDT 2025-04

Triumph has identified an error with TDT version 2025-04 (TOL #26996) that may cause headlight downloads on MY22 – MY25 Tiger 1200 models to fail. This will not cause any damage to the headlight hardware.

We are working on a resolution and expect to release a revised version of TDT by March 20th, 2025.

As an interim solution, any required headlight downloads can be completed by temporarily reinstalling TDT version 2025-03 which will remain active until a full fix is released. **TDT 2025-03 should only used for these headlight downloads.**

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.