



**Bulletin No.:** PIT6319B

**Published date:** 03/24/2025

## Preliminary Information

### PIT6319B Service High Voltage Message and No Heat

#### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	LYRIQ	2025	All	All	All	All
Cadillac	VISTIQ	2026	All	All	All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Condition</b>	<b>Service high voltage message. Heat begins to blow cold. P1C01 set in history. Charging reduced to 27% message Any or all of these symptoms may be found.</b>
<b>Cause</b>	<b>Software</b>

#### Correction:

**If P1C01 is in history do not attempt any repairs at this time.**

**Advise the customer that shutting the vehicle down and restarting should temporarily alleviate the concern, returning heat to the vehicle and allowing full charging.**

**It may take a few key cycles for the code to clear and the MIL to turn off.**

**Advise the customer that engineering is working on updated software to permanently resolve this issue.**

**A bulletin will be released when software is available.**

**If P1C01 is set current or the customer states that the concern has occurred multiple times, diagnose the vehicle following SI.**

#### Version History

<b>Version</b>	3
<b>Modified</b>	<b>01/15/2025 - Created on. 1/29/2025- Updated Correction. 03/24/2025 - Removed Blazer EV, OPTIQ and Equinox EV and added VISTIQ.</b>

 GM Global Brands

© 2025 General Motors. All Rights Reserved.