



**Bulletin No.:** PIT6053B

**Published date:** 03/27/2025

## Preliminary Information

### PIT6053B Diagnostic Tip - Frontview Grille Camera Washer Nozzle Leaking


#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN: from to</b>	<b>Engine:</b>	<b>Transmissions:</b>
Chevrolet	Silverado 1500 New (RPO J22, VIN Digit 5 = A / D)	2022	All All	All	All
Chevrolet	Silverado 1500	2023 - 2025	All All	All	All
Chevrolet	Silverado 2500HD	2024 - 2025	All All	All	All
Chevrolet	Silverado 3500HD	2024 - 2025	All All	All	All
GMC	Sierra 1500 New (RPO J22, VIN Digit 5 = H / U)	2022	All All	All	All
GMC	Sierra 1500	2023 - 2025	All All	All	All
GMC	Sierra 2500HD	2024 - 2025	All All	All	All
GMC	Sierra 3500HD	2024 - 2025	All All	All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Additional Options (RPO)</b>	<b>UV2</b>
<b>Condition</b>	<b>Some customers may comment that the Frontview Camera Washer Nozzle is leaking washer fluid.</b>
<b>Cause</b>	<p><b>Service Information or the EPC/parts catalog does not show that there is a one way check valve built into the windshield washer hose that connects to the washer pump.</b></p> <p><b>This check valve is to prevent washer fluid from leaking.</b></p>

#### Correction:

**If no other root cause is found, then the check valve is included with the windshield washer hose that connects to the washer pump (#1 below) and replace as necessary.**



**Version History.**

<b>Version</b>	<b>3</b>
<b>Modified</b>	<b>08/25/2023 - Created on. 10/02/2023 - Added Model year and updated correction information. 03/27/2025 - Updated Model Year and Added Models</b>