

RCA-86-25-001-1: Replace Secondary Driver Assistance Module, R1T

Rivian is initiating a customer satisfaction campaign for some model year 2022 R1T vehicles that were built with early revisions of the secondary driver assistance module that are susceptible to early failure. This results in multiple telltales being displayed to the driver and limited performance of the vehicle. Rivian will replace the module with an updated version. Rivian is launching this campaign for customer satisfaction and to ensure the quality of Rivian vehicles.

Document Type	Customer Satisfaction Campaign Bulletin	
Date	March 5, 2025	
Affected Region(s)	USA	
Affected Model(s)	R1T	
Model Year(s)	2022	
Approximate Build Dates	August 2021-March 2022	
Refer to Open Containments in ServiceOS to determine if this document applies to a specific vehicle.		
Vehicle System	86 - Driver Assistance	
Minimum Service Location	Service Center	

Required Parts

Part Number	Quantity	Engineering Name	Service Name/Notes
PT00000036-M	1	MODULE - ECU; ADAS; ASM	Module, Driver Assistance, Secondary

Attention: The parts listed in this table are only for unique steps that are called out in this bulletin. Some sections of this bulletin might refer to Service Manual procedures which require additional parts. Always review the bulletin and all potentially related Service Manual procedures before ordering parts and beginning work.

Procedure

- 1. Replace: Module, Driver Assistance, Secondary (refer to service manual procedure 863215010).
- 2. Reinstall all components that were removed for access and replace all non-reusable components. Refer to the service manual procedures referenced in this document for additional component reusability information and torque specifications.



Labor Code	Description	
RCA862500100	RCA-86-25-001 not applicable	
RCA862500101	Replace secondary driver assistance module	
Contact ServiceDocumentFeedback@rivian.com regarding labor codes and document content.		