

IAUPS004203

Update Prior to Sale

Authored Date	07/03/2025	
Doc No.	IAUPS004203	
Title	Removal of the Towbar	
Affected Vehicle(s)	Grenadier	SF023580 – SF023792
Prior to starting any reworks, please make sure you check the vehicle is affected by checking the VIN using Vehicle Simple Search in the Warranty System.		

Reason for this document

Issue: An issue has been identified on a small percentage of the affected vehicles where the incorrect towbar was delivered with the vehicle.

Cause: Incorrect process led to delivery error of the towbar.

Action: Follow the procedure below.

Workshop Procedure

Towbar Removal

Operation:	Repair Time:
Remove Towbar	0.1

Note:

- The procedure contains illustrations showing certain components removed to provide extra clarity.
- This procedure contains some variation in the illustrations depending on the vehicle specification, but the essential information is always correct.

Removal

1.

Open the Split Load Doors.

Refer to: [Split Load Doors \(Open and Close\) TOPIC0000001963](#)



IAUPS004203

Update Prior to Sale

2.

Note:

Check the part number on the box and make sure the towbar removed is EI-0000012743



Remove the towbar.

3.

Close the Split Load Doors.

Refer to: [Split Load Doors \(Open and Close\) TOPIC0000001963](#)

4.

Release the vehicle.

IAUPS004203

Update Prior to Sale

Change History

Reference No.	Date	Description
IAUPS004203	07/03/2025	First release

