

VEHICLE QUARANTINE N995 – OCCUPANT CLASSIFICATION SYSTEM

VEHICLE QUARANTINE N995 – OCCUPANT CLASSIFICATION SYSTEM	
AFFECTED MODEL	25MY Range Rover Sport SV
VOLUME AFFECTED	37 USA
REPAIR	<p>An issue has been identified where the incorrect calibration weight has been used in the manufacturing process of the Restraints Occupant Classification System Module (OCS) for certain Range Rover Sport SV Seats. This many results in the passenger airbag not being disabled in line with FMVSS 208/CMVSS 208 when a child seat is installed, and the airbag may incorrectly be deployed in the event of a crash.</p> <p>New front row seat OCS modules will need to be installed.</p>
REPAIR TIME	1.1 hr + DIDO
CAMPAIGN LAUNCH	Vehicle Quarantine Notice was issued on March 7th, 2025
NOTES	<p>Retailers are required to Quarantine all affected vehicles that are within your control and refrain from releasing the vehicles for vehicle sale until they are repaired</p> <p>A service bulletin will be released to communicate the repair procedure when parts arrive in market.</p> <p>8 affected vehicles are in retailer stock.</p>