

Subject		Market
Rattle Noise Near Hybrid Motor in D or P		USA
Service Category	Section	
Engine/Hybrid System	Hybrid/Battery Control System	
Applicability		
22-25 MY Tundra HV, 23-25 MY Sequoia HV		

### APPLICABLE VEHICLES

2023-2025	Sequoia HV	2022-2025	Tundra HV
-----------	------------	-----------	-----------

### CONDITION

Some 22-25 MY Tundra HV and 23-25 MY Sequoia HV vehicle may exhibit a condition where there is a rattling noise, near the hybrid motor, when the vehicle is Ready on, in Drive or Park.

### RECOMMENDATIONS

If the condition is identified, please halt all diagnostics and create a TAS case. If on a weekend or holiday, please continue with diagnostics and repair, and contact TAS on the next available business day.

### LINK REFERENCES

This Tech Tip does not contain any link references