

2025 Ascent

1.COMPLAINT: REAR SCREEN FLICKERS AND HAS LINES ACROSS THE DISPLAY

CAUSE: INTERNAL FAULT

CORRECTION: INSTALL NEW DISPLAY 0.50HR 0.30 approved. I will forward this to Spyder for warranty.

2024 Ontour

2. Concern: The rear screen does not work. There are line on the screen that go in and out.

Cause: Defective screen

Correction: Needs to be replace rear screen

Time: 0.60 approved. Requested both screens replaced.