



2025-03-24



M1675: HISTORIC DIAGNOSTIC TROUBLE CODE (DTC) B216209

Repair Procedure

1. If DTC B216209 is found to be CURRENT, follow troubleshooting steps in the EDM.

Date	Rev	Revision (Rev) Description
2025-03-24	-	Initial release

This bulletin inform dealers that the Body Control Module (BCM) Diagnostic Trouble Code (DTC) B216209 can be induced by operator input even though there is no actual fault.

NOTE

Required Dealer Action

Category	Description	Required
1	Must Perform Repair	<input type="checkbox"/>
2	Repair If Presenting Symptom	<input type="checkbox"/>
3	Feature Pack- Customer/Dealer Paid	<input type="checkbox"/>
4	Informational Purposes Only	<input checked="" type="checkbox"/>

2025 Softail: Heritage Classic (FLHC), Low Rider S (FXLRS), Low Rider ST (FXLRST)

All markets affected.

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

[illegible]