

Technical Service Bulletin (TSB) Blind Spot Monitoring System Warning On

REFERENCE:	TSB: 08-100-25 GROUP: 08 - Electrical	Date:	April 4, 2025	REVISION:	—
VEHICLES AFFECTED:	2024 - 2025 (KM) Jeep Wagoneer S This bulletin applies to vehicles built on or after May 22, 2024 (MDH 0522XX) and on or before November 28, 2024 (MDH 1128XX).			MARKET APPLICABILITY: <div><input checked="" type="checkbox"/> NA<input type="checkbox"/> MEA <input type="checkbox"/> SA<input type="checkbox"/> IAP <input type="checkbox"/> EE<input type="checkbox"/> CH</div>	
CUSTOMER SYMPTOM:	Customer may experience the following: <ul style="list-style-type: none">Blind Spot System Off/Service Blind Spot System/Blind Spot Temporarily Unavailable warning lights on in Instrument Panel Cluster (IPC).Blind Spot Monitoring inoperative.				
CAUSE:	Incorrect software level in Mid-Range Radar				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 25-056, date of issue April 04, 2025. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves replacing the Mid-Range Radars.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-22-01-96	Module, Radar Mid Range Radars - Replace (0 - Introduction)	6 - Electrical and Body Systems	1.7 Hrs.
Failure Code	ZY	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
4 (AR)	04699069AH	Radar	—

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Replace the Mid-Range Radars. Refer to the detailed service procedures listed in DealerCONNECT>Service Library>Service Info under: 08 - Electrical / 8B - Driver Assistance / Assistance System Components / Radars / Removal and Installation.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.