

Volvo Car USA LLC

Technical Journal

Technical Journal Title ADPM Prior Approval		Ref. No. TJ 37290.1.0	
Issuer (Dept.) Technical Service		Issue Date 2/27/25	Status Date 3/10/25
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA		Function Group 3880
Function Description Support systems, autonomous drive		Page Page 1 of 1	

DESCRIPTION:

If the ADPM is in need to be replaced, follow advice under “Service”.

ADPM = Autonomous Drive Primary Module

CSC Customer Symptom Codes

Code	Description
1Z	Service/repair/Software update failed
22	Diagnostic communication/Wired diagnostic connection to vehicle does not work
2V	Technician information/Software/Vehicle communication/Not for warranty use

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
356							2025-2099		-	202417-209952

SERVICE:

In most cases the ADPM does not need to be replaced.

Support can be provided by your local technical helpdesk or from Volvo Cars central technical helpdesk.

Contact your local technical helpdesk to get technical prior approval or assistance, using your normal escalation process.

Warranty claim info:

No warranty claim is accepted for this TJ.

VEHICLE REPORT:

Yes, please submit a Vehicle Report. Use concern area “Vehicle Report” and sub concern area “Support needed” use function group 3880. Add the TJ number in the title of the report as a reference.