

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title Clicking sound from transmission area		Ref. No. TJ 35732.1.0	
Issuer (Dept.) Technical Service		Issue Date 2/25/25	Status Date 3/10/25
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA		Function Group 4300
Function Description Gearbox		Page Page 1 of 2	

DESCRIPTION:

This technical journal contains a movie which describes how the CPA (Central Pendulum Absorber) moves inside the torque converter.

This animated movie is a complement to information found in VIDA and TRIP information to help illustrate the normal functioning of the CPA.

VIDA = Volvo Information and Diagnostics for Aftersales

TRIP = Technical Reference Information Portal

CSC Customer Symptom Codes

Code	Description
F6	Complete vehicle/Unusual noise/During deceleration
C3	Automatic transmission/Unusual noise

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224	L1	BL1KERS					2022-9999		-	202122-999952
227	L1	BL1KERS					2022-9999		-	202122-999952
236	06	B06KERS					2022-9999		-	202022-999952
236	L1	BL1KERS					2022-9999		-	202022-999952
238	06	B06KERS					2022-9999		-	202122-999952
246	06	B06KERS					2022-9999		-	202122-999952
246	L1	BL1KERS					2022-2024		-	202122-202322
256	06	B06KERS					2023-9999		-	202222-999952
256	L1	BL1KERS					2023-2024		-	202222-202322
536	K9	BK9KERS					2023-2023		-	202222-202322
536	L1	BL1KERS					2023-9999		-	202222-999952



Technical Journal 35732.1.0

SERVICE:

Do not replace any parts due to this sound.

This is considered a normal operating characteristic/function of the vehicle.

Warranty claim info:

No warranty accepted for a job described in this TJ.

VEHICLE REPORT:

N/A