



SSM 53571 2025 Expedition/Navigator - DTCs B1208:2A, B14D1:12, B1060:12 And B1521:12 Stored In The DSM

Some 2025 Expedition/Navigator vehicles may exhibit diagnostic trouble codes (DTCs) B1208:2A, B14D1:12, B1060:12 and B1521:12 in the drivers seat module (DSM) when a diagnostic self-test is performed. This may be due to the software within the DSM. These DTCs should be ignored if no other DTCs are present in the DSM and no customer concerns are present. Address any other DTCs present using normal Workshop Manual (WSM) diagnostics. Replacement or reprogramming of the DSM will not resolve this condition at this time.