



SSM 53579 2024-2025 F-150 - Equipped With A Lower Active Grille Shutter - Illuminated MIL With DTC P05B0 Stored In The PCM

Some 2024-2025 F-150 vehicles equipped with a lower active grille shutter may exhibit an illuminated malfunction indicator lamp (MIL) with diagnostic trouble code (DTC) P05B0 stored in the powertrain control module (PCM). This may be due to the lower active grille shutter. To correct this condition, install a new lower active grille shutter prior to doing additional diagnosis. Refer to the Workshop Manual (WSM), Section 501-02 Front End Body Panels > Removal and Installation > Active Grille Shutter. For claiming, use causal part 8475 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.