



Bulletin No.: PIC6593A
Published date: 04/11/2025

Preliminary Information

PIC6593A DTC P0621 - Service Charging System Displayed

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Buick	Encore GX	2024 - 2025	All	All	All
Chevrolet	Trailblazer	2024 - 2025	All	All	All

Involved Region or Country	North America
Condition	Customers may comment that the CEL/MIL is illuminated along with a service charging system message. Technician may find DTC P0621 set as current or history.
Cause	Engineering is currently investigating.

Correction:

Please follow the diagnostic test procedures outlined in SI for DTC P0621.

If the test results do not directly identify a functional fault, other than a warning message/light, do NOT replace any parts at this time.

Engineering is currently investigating.

In the meantime, please advise customer they may continue to drive the vehicle

The PI will be updated or replaced with TSB once a determination has been made.

Version History

Version	2
Modified	02/13/2025 - Created. 04/08/2025 - Updated models

