

REFERENCE:	TSB: 23-016-25 GROUP: 23 - Body	Date:	April 8, 2025	REVISION:	-
VEHICLES AFFECTED:	2022 - 2024 (B1) Jeep Renegade (Brazil) This bulletin applies to vehicles built on or before July 19, 2023 (MDH 0719XX).			MARKET APPLICABILITY:	
				<input type="checkbox"/> NA	<input type="checkbox"/> MEA
				<input checked="" type="checkbox"/> SA	<input type="checkbox"/> IAP
				<input type="checkbox"/> EE	<input type="checkbox"/> CH
CUSTOMER SYMPTOM:	Customers may experience one or more of the following: <ul style="list-style-type: none"> Squeaking noise coming from the rear spoiler. Rear spoiler is loose. 				
CAUSE:	Lack of adhesion				

REPAIR SUMMARY:

This bulletin involves installing a new spoiler.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
23-02-06-9A	Paint And Replace Rear Spoiler (0 - Introduction)	6 - Electrical and Body Systems	2.1 Hrs.
Failure Code	ZZ	Service Action	

SPARE PARTS:

NOTE: Only use one PN for the color (Base, Metallic or Pearlsh).

Qty	Part No.	Description	Notes
1	100236695 - SA 7GD51TZZAA - MOPAR	Spoiler	
50ml	7088970 - SA 68422148AA - MOPAR	Base Color	(Refund only)
50ml	7088971 - SA 68422184AA - MOPAR	Metallic Color	(Refund only)
50ml	7089983 - SA 68422151AA - MOPAR	Pearlish Color	(Refund only)
50ml	7088972 - SA 68422150AA - MOPAR	Varnish	(Refund only)

DIAGNOSIS:

If the customer describes any of the symptoms listed above in the customer symptom section, and it is in the range of vehicles affected and identified that the noise is coming from the spoiler, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Remove the old spoiler. Refer to the detailed procedures listed in DealerCONNECT>Service Library>Service Info> under: 7210G76 - Aerofolio/Spoiler sobre a tampa traseira/porta-malas/cabine - remocao/recolocacao.
2. Paint the new spoiler.
3. Install the new spoiler. Refer to the detailed procedures listed in DealerCONNECT>Service Library>Service Info> under: 7210G76 - Aerofolio/Spoiler sobre a tampa traseira/porta-malas/cabine - remocao/recolocacao.

NOTE: After applying this TSB, it is not necessary to send DID-I or DID-A.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.