



SIB 51 01 25

SERVICE SOLUTION: Unlocking the steering lock is not possible with keyless ride

2025-04-03

MODEL

Model	Model Description	Model Code
KA1	R 1300 GS	0M23
KA2	R 1300 GS Adventure	0M33
K06	CE 02	0C73

SITUATION

When the vehicle key is recognized; however, the steering lock will not unlock and the keyless ride control unit hums briefly.

Continued analysis is required.

PROCEDURE

For units that are experiencing this complaint:

1. **DO NOT** perform any repair attempts.
2. **SUBMIT A TSARA** case for an IRAP Next session for analyzation

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Supporting Materials

[picture_as_pdf 51 01 25 SESO unlocking steering lock not possible.pdf](#)

