



SIB 61 05 25

SERVICE ACTION: Software Update - Central Locking

2025-04-03

MODEL

Model	Model Description	Model Code
K35	R 18 B	0L33
K35	R 18 Transcontinental	0L43

The affected vehicles have been marked with campaign number **0061670000** in AIR.

In order to determine if a specific motorcycle is affected by this campaign, it will be necessary to verify the vehicle VIN in AIR (Aftersales Information Research). Based on the response of the system, either proceed with the repair or take no further action. Please note, open campaigns or vehicle stops may not appear in DCS Warranty Vehicle Inquiry or sales systems until 24-72 hours after they are announced, therefore AIR is always the recommended method for determining open campaigns and vehicle stops.

SITUATION

For affected vehicles with Option 417 (central locking system), when parked, under certain situations due to a software error, the top case can be unlocked without the radio key in range.

The affected vehicles have been placed under the delivery stop STOP610024 associated with campaign number 0061670000, which will be lifted upon completion of this technical campaign.

Vehicles will be produced without the fault estimated during calendar week 15 (week of April 6-12) series production.

PROCEDURE

For vehicles that have not yet been delivered, the service action must be completed before vehicle handover. If the service action cannot be completed due to a parts, software, or special tool shortage, the service action then must be performed during the next possible workshop visit when parts, software, or special tools become available. In such instances where work cannot be performed, it is essential to inform the customer of the situation.

In all instances in which the vehicles have already been handed over to customers, the Technical Campaign must be performed at the next workshop visit.

The software version of the vehicle must be programmed to I-level K001-25-03-505 available with ISTA version 4.52.4X, in accordance with the model-specific repair instructions "61 00 510 – Programming vehicle control units"

Check to make sure you have the latest ISTA version before performing this software update.

NOTICE: When programming, it is essential to make sure that the FASTA data is transferred correctly to the back end. FASTA data is used to make sure the correct performance of the Service Campaign was used for warranty purposes. Incorrect data will result in delays of the credit or chargeback of the requests.

CLAIM INFORMATION

Please submit claims via the normal claim process using the information below:

Copyright ©2025 MOTORRAD USA, a division of BMW of North America, LLC. All Rights Reserved

Defect code

00 61 67 00 00	Update Software
----------------	-----------------

Labor Operation

00 60 426	Technical campaign standard 3	5 FRU
+00 60 926	Technical campaign standard 3	4 FRU
46 52 510	Mounting and dismounting the rear-wheel stand with special tools (for motor-bikes without a center stand)	1 FRU

FRUs includes all repair procedures to complete the task with allowance for necessary ancillary tasks (e.g., visual inspection, lubrication, cleaning parts etc.) and administrative tasks.

Labor operation code 00 60 426 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation instead.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Supporting Materials

[picture_as_pdf 61 05 25 SA Software update central locking.pdf](#)

