



SIB 61 06 25

SERVICE SOLUTION: R 1300 Models Comfort Flashing Cannot Be Deactivated

2025-04-11

MODEL

R 1300 models with I-Level X001-25-03-505

SITUATION

The comfort flashing function is deactivated in the instrument cluster settings, the function reactivates automatically after a few seconds. This means that comfort flashing cannot be deactivated.

Due to a software error in I-level X001-25-03-505.

PROCEDURE

Currently, no measure is available.

I level X001-25-07-500 will fix the complaint and is estimated to be available with ISTA version 4.54.3x.

QUESTIONS REGARDING THIS BULLETIN

| | |
|---------------------|---|
| Technical inquiries | Contact the BMW Technical Support Group via TSARA |
| Warranty inquiries | Submit an IDS ticket to the Warranty Department |
| Parts inquiries | Submit an IDS ticket to the Motorrad Parts Department |

Supporting Materials

[picture_as_pdf 61 06 25 SESO Comfort flashing cannot be deactivated.pdf](#)

