



SIB 71 01 25

Service Action: Replace Emissions Label

2025-04-03

MODEL

Model	Model Description	Model Code
KM3	M 1000 R	0P53

The affected vehicles have been marked with campaign number **0071240000** in AIR.

In order to determine if a specific motorcycle is affected by this campaign, it will be necessary to verify the vehicle VIN in AIR (Aftersales Information Research). Based on the response of the system, either proceed with the repair or take no further action. Please note, open campaigns or vehicle stops may not appear in DCS Warranty Vehicle Inquiry or sales systems until 24-72 hours after they are announced, therefore AIR is always the recommended method for determining open campaigns and vehicle stops.

SITUATION

The Emission Label control information for US Model code (0P53) contains faulty EVAP and Permeation data.

The affected vehicles have been placed under the delivery stop STOP710017 associated with campaign number 0071240000, which will be lifted upon completion of this technical campaign.

PROCEDURE


For vehicles that have not yet been delivered, the service action must be completed before vehicle handover.

In all instances in which the vehicles have already been handed over to customers, the Technical Campaign must be performed at the next workshop visit.

The correct Emission label is **BEING SHIPPED TO DEALERS DIRECTLY** and must be installed at the location on the frame as shown. The previous label does not need to be removed, carefully clean the surface before the new label is affixed.

DO NOT USE: Alcohol based solvent or brake clean to clean to clean surface.

Install new label exactly on top of the original label



CLAIM INFORMATION

Please submit claims via the normal claim process using the information below:

Defect code

00 71 24 00 00	Replace Emission Label
----------------	------------------------

Labor Operation

00 60 350	Replace Label	4 FRU
+00 60 725	Replace Label	3 FRU

FRUs includes all repair procedures to complete the task with allowance for necessary ancillary tasks (e.g., visual inspection, lubrication, cleaning parts etc.) and administrative tasks.

Labor operation code 00 60 350 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation instead.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Supporting Materials

[picture as pdf 71 01 25 - SA- M 1000 R Replace Emission Label.pdf](#)

