

R232 - Seat Backrest Of Front Seat Collides With Draft Stop

Topic number	LI91.10-P-079211
Version	1
Function group	91.10 - Front seats
Date	4/21/25
Validity	Valid for model series 232.
Reason for change	

Complaint

Seat backrest of front seat collides with the installed draft stop in the rearmost position.

Attachments	
File	Description
Berührung Windschott mit Sitz.jpg	
	
Sitz Beschädigung.jpg	



Cause

The seat can be adjusted too far to the rear beyond the correct limit (combination of seat adjustment and seat back-rest angle).

Remedy

Remedy SW A2329038302 for the SEAT control unit to limit the adjustment range of the mechanical seat components.

Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

Symptoms
Body > Seat > Seat adjustment > Function error

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note