

Technical Service Bulletin (TSB)
Rear Door Belt Molding Loose

REFERENCE:	TSB: 23-017-25 GROUP: 23 - Body	Date:	April 17, 2025	REVISION:	—
VEHICLES AFFECTED:	2022 - 2024 (B1) Jeep Renegade This bulletin applies to vehicles built on or before May 30, 2024 (MDH 0530XX).	MARKET APPLICABILITY:			
		<input type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> EE <input type="checkbox"/> IAP <input checked="" type="checkbox"/> SA <input type="checkbox"/> CH			
CUSTOMER SYMPTOM:	Customers may experience the following: <ul style="list-style-type: none"> The weather stripping (belt molding) on the rear doors is loose or detaching. 				
CAUSE:	Manufacturing issue				

REPAIR SUMMARY:

This bulletin involves possibly replacing one or both of the rear door sill moldings (belt moldings).

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
23-51-16-9K	Replace Left or Right - One Side	6 - Electrical and Body Systems	0.2 Hrs.
23-51-16-9L	Replace - Both Sides (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	52250018 - SA 68725192AA - Mopar	Weatherstrip, Rear Door Belt Outer	Right
1 (AR)	52250019 - SA 68725255AA - Mopar	Weatherstrip, Rear Door Belt Outer	Left

DIAGNOSIS:

If the customer describes a symptom/condition above, perform the Diagnostic Procedure.

1. Verify the door sill molding (weatherstrip, door window belt molding) on the rear doors (right/left) is loose or detaching [Fig. 1](#).



Fig. 1
Loose Or Detaching Molding

2. Was the door sill molding (weatherstrip, door window belt molding) on the rear doors (right/left) loose or detaching [Fig. 1](#)?
 - YES >>> Proceed to [Step 1](#) of the Repair Procedure.
 - NO >>> This bulletin does not apply.

REPAIR PROCEDURE:

1. Replace one or both rear door sill moldings as required. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info> 7010D26 - Pestana (externa) do vidro da porta lateral (uma) - remocao/recolocacao.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.