



Service Bulletin

Bulletin No.: 25-NA-067

Date: March, 2025

INFORMATION

Subject: Information on Service High Voltage Message and No Heat - DTC P1C01

This bulletin replaces PIT6319A for these models. Please discard PIT6319A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission :
		from	to	from	to		
Cadillac	OPTIQ	2025	2025	—	—	All	All
Chevrolet	Blazer EV	2025	2025				
	Equinox EV	2025	2025				

Involved Region or Country	North America, Chile, Brazil, Colombia, Ecuador, Middle East
Condition	Some customers may comment on Service High Voltage Warning Message and vehicle in setting P1C01
Cause	The cause of the condition may be software anomalies.
Correction	<p>For the effected vehicles above, GM is recommending that dealers utilize Vehicle Wide Programming to perform and confirm all modules are updated when customer vehicles are brought in for any service or at the customer request (Bumper-to-Bumper Warranty or maintenance).</p> <p>Note: For the effected vehicles above in New Vehicle Inventory, one software update is allowed prior to sale and should be completed close to delivery to the customer</p> <p>Technicians are to utilize Vehicle Wide Programming to update all modules. Please refer to 24-NA-113: Vehicle Wide Programming Instructions for information on programming.</p>

Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Important: This technical service bulletin (TSB) can only be completed by certified repair facilities who have met all specific training, tool and equipment requirements pertaining to the vehicle Brand and Model serviced. Repairs must be performed by a technician who has successfully completed the required training.

1. Verify the vehicle is setting P1C01.
 - DO NOT replace any parts.
2. Program the BECM through SPS2 VWP programming.
 - Refer to Service Bulletin **24-NA-113:** Vehicle Wide Programming Instructions for information on programming.

Parts Information

No parts are required for this repair.

Warranty Information

For information on the Warranty Claim Code, refer to **24-NA-132**: Warranty Administration- Claim *Submission*.

Version	1
Modified	Released March 21, 2025

