

MAS004697 MCL 25-23

Circular Letter

FROM: Maserati TSO

TO: Maserati Network



PERSONAL SERVICE LAB

MASTERS OF CARE

MC20 Cielo - Serviceability of the fuel tank door lock



DATE: April 11, 2025

This communication is intended to provide important information on the serviceability of the fuel door lock/unlock mechanism. If you experience any problems, you can now replace it instead of the entire rear fender.


Problem Description

In few cases, it has been observed that it is not possible to open the fuel door due to a defective locking/unlocking mechanism.

Component Details

The following P/N is available:

- #670355090 = FUEL END CAP REPAIR KIT (Parts Catalogue -> Section #09.06-1 -> Item #19)



Please always refer to the Technical Documentation for the latest updates or contact the Maserati Helpdesk.

Workshop procedure

The procedure for replacing the fuel door lock/unlock mechanism is published in the Technical Documentation; the reference is:

- #09.06.020 – FUEL TANK DOOR REPAIR KIT (0.50 h).

Special Tools

No special tools are required for this procedure.