



SSM 53674 2021-2024 Bronco - Paint Wear On The Top Inner Edge Of The Tailgate

Some 2021-2024 Bronco vehicles may exhibit paint wearing along on the top inner edge of the tailgate where the rear window weather strip contacts the tailgate. This may be due to the accumulation of dirt between the rear window seal and tailgate. Inform customers that engineering is aware of this condition and is currently working on a solution which is expected in Q3 2025. Schedule a service visit for customers when the repair is available in Q3 2025. Monitor OASIS for additional information.