



## **SSM 53677 2025 Bronco - DTC U0137 Stored In The IPC After Trailer Tow Package Install**

Some 2025 Bronco vehicles may exhibit diagnostic trouble code (DTC) U0137 stored in the instrument panel cluster (IPC) after installation of the dealer installed option (DIO) trailer tow package. To correct this condition, download and run the latest version of the towbar configuration application using the latest version of the Ford Diagnosis and Repair System (FDRS) scan tool. For claiming, use causal part 15A416 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.