

ICC5 Erroneous Electric Power Steering Warning Message

Issue:

- The ICC5 Connect5 ECU erroneously sends out these popup messages on the cluster
- All software development has ended for the ICC5 so there will not be a fix for this
- SS 3176-FTL for Freightliner and SS 784-WST for Western Star

Solution:

For vehicles with a diesel engine neither of these popups were intended to be displayed, so they can be cleared using the middle button on the left side of the steering wheel.

For eM2 or eCascadia, the red message was never intended to be displayed and can be cleared using the middle of the left side of the steering wheel. However, if you get the amber popup then the vehicle should be taken to an authorized service center to have the steering system diagnosed

