

SS 784-WST ICC5 Erroneous Electric Power Steering Warning Message

Applicable Vehicles

X Series Western Star vehicles with optional ICC5

Symptoms

On diesel powered vehicles with a particular variant of Instrument Cluster, ICC5, two messages relating to electric vehicle malfunctions may erroneously appear. These are nuisance messages only and do not indicate actual fault conditions.




Figure 1

Issue

For vehicles built up to model year 2023 either of the warning messages pictured in Figure 1 could be displayed. The red message "Steering Behavior Changed Service Immediately" was never intended to show up on any of these vehicles.

For all vehicles with the ICC5 built after model year 2023 only the warning message in the amber color "Power Steering Not Functional Service Vehicle" could be displayed.

In both groups mentioned above, the warning messages were never intended to be displayed on the ICC5 for X-Series Western Star Vehicles.


Solution

If the X Series Western Star vehicle encountering either of the warning messages, then use the middle button on the left side of the steering wheel to clear either message. Both messages should be considered nuisance messages as neither apply to the X Series Western Star Vehicles.

Labels :



Add tags



Comment