

SS 89 TBB C2 Windshield Stress Crack Info only

Applicable Vehicles

C2

Symptoms

Stress Cracks Lower Corner Rivet Area

Issue

Insulation, the Spacer were installed backwards. The Thicker part of the spacer should be between the Windshield and the Body. The BOM has the installation

Solution

Replace under normal warranty. Any units after 2/21/25 or Body number 2560660 need to be reported to TBB or Create a ticket in Salesforce

Labels :

Saf-T-Liner

Add tags



0 Kudos

Comment

Powered by
Khoros 