

# SS 765-WST ECP Solenoid Valve Interim Replacement Parts

## **Applicable Vehicles**

47X and 49X vehicles with ECP solenoid valves

## **Symptoms**

ECP solenoid failures that require replacement of the solenoid - for example, lift axle does not raise or drop.

## **Issue**

Current solenoid parts have been replaced with an interim, soft-tooled part ahead of production changeover to a revised ECP solenoid. These soft-tooled parts should be used instead of the parts listed in Excelerator.

## **Solution**

The following two parts have been released and are available in the PDCs:

12-33827-000 replaces solenoid 12-29442-000

12-33827-001 replaces solenoid 12-29442-001

Labels :

47X

49X

57X

Add tags



Comment

