

## SERVICE ACTION D001 – APMU HOSE CLEARANCE TO HEATSHIELD

SERVICE ACTION D001 – AUTOMATIC PRESSURE MAINTENCE UNIT (APMU) HOSE CLEARANCE TO HEATSHIELD	
AFFECTED MODEL	25MY Defender OCTA variants only
VOLUME AFFECTED	150 USA 15 CAN
REPAIR	A concern has been identified where the Automatic Pressure Maintenance Unit (APMU) may have been installed with a clash condition between the APMU hose and heatshield. Rubbing of the APMU hose on the heatshield could create pressure loss and / or fluid leak on 6D dynamic suspension system over a period of time. A modification to the APMU heatshield is required.
REPAIR TIME	0.7 hr + DIDO
CAMPAIGN LAUNCH	April 9th, 2025
NOTES	Retailers are required to repair all affected vehicles in their control before sale and sold vehicles at the next service visit. Affected vehicles are shown in the warranty portal and TOPIx immediately and in BBSS effective April 10th. Retailer unsold stock CAN 9 and USA 36.