

CHECKING PHEV COOLANT LEVEL

Customer Voice:

- Electrical system failure light is on the instrument cluster.

Technical Description:

- The coolant level for the PHEV system is possibly low causing the warning.

Status:

- During initial diagnosis for a PHEV electrical system failure light, the PHEV coolant check is missed by technicians not familiar with the system.
- Please follow the TOPIx instructions for checking the coolant level for the PHEV unit below.
- Check and top-up the coolant to the MAX mark then add 150ml to the level as shown in the image below. (Step 26)



Refer to TOPIx 613-02: Cooling System - [+] PHEV ,
General procedures Battery Cooling System Draining,
Filling and Bleeding

Range Rover

- 24-25MY Range Rover (PHEV ONLY)
- 24-25MY RR Sport (PHEV ONLY)

