

<b>Reference</b>	SSM76301
<b>Models</b>	Discovery Sport / L550 New Range Rover Evoque / L551
<b>Title</b>	Front Stabiliser Bar Link - Noisy
<b>Category</b>	Chassis
<b>Last modified</b>	07-Apr-2025 00:00:00
<b>Symptom</b>	304000 Suspension System

**Content**      **Model / Model Year / Derivative:**

Discovery Sport / 15MY onwards / All  
Evoque / 19MY onwards / All

**Situation:**

JLR Engineering investigations have identified a knocking noise coming from the front stabiliser bar link.

**Action:**

Refer to the service request below.

**Service Request:**

To assist Engineering in identifying the root cause of specific noises, follow these steps:

1. Conduct a Safe Road Test:

- Drive the vehicle over uneven and broken surfaces.
- During the test, record any 'rattling' or 'knocking' noises from the front stabilizer bar link.

2. Raise an Electronic Product Quality Report (EPQR):

- Include the following information:
- Reference to CES\_210 (CSS Group)
- Reference to P386532 (Project number)
- Reference to this SSM (76301)
- Sound file/video of any 'rattling' or 'knocking' noises recorded during the road test
- Confirmation of the type of noise heard ('rattling' or 'knocking')
- Confirmation of the road surface the vehicle was driven on when the noise was heard
- Confirmation of the vehicle speed at the time the noise was heard

3. Update the EPQR:

- Detail all completed repair actions.

(Ref 000386532 / 4626)

anBhdHRicnM7MjAyNS0wNC0wOVQxMjcyMC4zODRaOzE2NS4yMjUuMzguMjUyOw==