

Reference	SSM76302
Models	E-PACE / X540
Title	Front Stabilizer Bar Link - Noisy
Category	Chassis
Last modified	07-Apr-2025 00:00:00
Symptom	304000 Suspension System

Content **Model / Model Year / Derivative:**

E-Pace / 18MY onwards / All

Situation:

JLR Engineering investigations have identified a knocking noise coming from the front stabiliser bar link.

Action:

Refer to the service request below.

Service Request:

To assist Engineering in identifying the root cause of specific noises, follow these steps:

1. Conduct a Safe Road Test:

- Drive the vehicle over uneven and broken surfaces.
- During the test, record any 'rattling' or 'knocking' noises from the front stabilizer bar link.

2. Raise an Electronic Product Quality Report (EPQR):

- Include the following information:
- Reference to CES_210 (CSS Group)
- Reference to P386532 (Project number)
- Reference to this SSM (76302)
- Sound file/video of any 'rattling' or 'knocking' noises recorded during the road test
- Confirmation of the type of noise heard ('rattling' or 'knocking')
- Confirmation of the road surface the vehicle was driven on when the noise was heard
- Confirmation of the vehicle speed at the time the noise was heard

3.Update the EPQR:

- Detail all completed repair actions.

(Ref 000386532 / 4626)

anBhdHRicnM7MjAyNS0wNC0wOVQxMjcyMzoyMS4xNzlaOzE2NS4yMjUuMzguMjUyOw==